

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-040"/>	Response	Informed the department that these types of activities were not permissible.
Date Received	<input type="text" value="7/18/2007"/>		
Date Response	<input type="text" value="7/18/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Hospital Creek"/>		
Location	<input type="text" value="Fire Station 13 Hollister"/>		
Reported Discharge	<input type="text" value="Dirty water"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Fire Dept."/>	Follow-up	
Observations	Dirt stains in parking lot leading to storm drain. Appears they washed equipment and the wash water flowed into Hospital Creek.		

Case #	<input type="text" value="07-042"/>	Response	Spoke with contractors who were using water to help with compaction in filling up a hole from a removed underground storage tank.
Date Received	<input type="text" value="7/31/2007"/>		
Date Response	<input type="text" value="7/31/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Orcutt"/>		
Location	<input type="text" value="Clark and Orcutt SW corner"/>		
Reported Discharge	<input type="text" value="pumping water into UST at gas station"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Contractor"/>	Follow-up	
Observations	No discharge of concern.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-043"/>	Response	Sampled discharge to determine the source. Results indicated high levels of nitrate. Forwarded to David LaCaro at CCRWQCB for follow-up enforcement.
Date Received	<input type="text" value="8/2/2007"/>		
Date Response	<input type="text" value="8/2/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Dave LaCaro"/>		
Watershed	<input type="text" value="Atascadero"/>		
Location	<input type="text" value="1358 Anderson Lane"/>		
Reported Discharge	<input type="text" value="Ag runoff"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Nursery"/>	Follow-up	
Observations	Runoff from nursery discharging to creek via a drainage ditch along side the road.		

Case #	<input type="text" value="07-044"/>	Response	Left door hanger/ Construction pamphlet and card.
Date Received	<input type="text" value="8/9/2007"/>		
Date Response	<input type="text" value="8/9/2007"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Atascadero"/>		
Location	<input type="text" value="in front of 4646 Mint Ln."/>		
Reported Discharge	<input type="text" value="Cement Washout"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Homeowner"/>	Follow-up	
Observations	Cement washout in gutter.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-045"/>	Response	Even though the complaint was not corroborated, took the oppurtunity to discuss concerns with cars owner. Left Creek Concern pamphlet.
Date Received	<input type="text" value="9/14/2007"/>		
Date Response	<input type="text" value="9/14/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="San Ysidro Creek"/>		
Location	<input type="text" value="1221 E. Valley Rd."/>		
Reported Discharge	<input type="text" value="Dripping Car fluids"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Resident"/>	Follow-up	
Observations	Car stored on bridge above creek. No discharge observed.		

Case #	<input type="text" value="07-046"/>	Response	Spoke with resident and gave pamphlets.
Date Received	<input type="text" value="9/14/2007"/>		
Date Response	<input type="text" value="9/14/2007"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="San Ysidro Creek"/>		
Location	<input type="text" value="1225 E. Valley Rd."/>		
Reported Discharge	<input type="text" value="Cement Washout"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Resident"/>	Follow-up	
Observations	Cement washout coming down driveway into the street.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-0461"/>	Response	<input style="width: 95%;" type="text" value="Discharge of sewage into yard from uncovered sewerline clean-out. Forwarded to County Environmental Health Services (EHS)"/>
Date Received	<input type="text" value="9/18/2007"/>		
Date Response	<input type="text" value="9/18/2007"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Hiromi Dugan"/>		
Watershed	<input type="text" value="IV Beach"/>		
Location	<input type="text" value="6772 Sabado Tarde Rd."/>		
Reported Discharge	<input type="text" value="Sewage"/>	Number of Follow-ups	<input type="text" value="1"/>
Responsible	<input type="text" value="Resident"/>	Follow-up	<input style="width: 95%;" type="text" value="9/19/2007 Hiromi Dugan (EHS) sent homeowner a Notice of Violation dishcharge eliminated and it was cleaned up."/>
Observations	<input style="width: 95%;" type="text" value="Sewage in yard in front of house."/>		

Case #	<input type="text" value="07-047"/>	Response	<input style="width: 95%;" type="text" value="Spoke with Homeowner and gave pamphlets. Homeowner assured me he doesn't dump dirt over into creek area."/>
Date Received	<input type="text" value="9/24/2007"/>		
Date Response	<input type="text" value="9/24/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value=""/>		
Watershed	<input type="text" value="Maria Ygnacio"/>		
Location	<input type="text" value="5193 Walnut Park Dr."/>		
Reported Discharge	<input type="text" value="Dirt being dumped"/>	Number of Follow-ups	<input type="text" value="0"/>
Responsible	<input type="text" value="Resident"/>	Follow-up	<input style="width: 95%;" type="text" value="None required"/>
Observations	<input style="width: 95%;" type="text" value="No dirt discharges and no visible problems at site."/>		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-048"/>	Response	Projec Clean Water Staff met with Valley Club Greenskeeper asked him to have the small pile of hydroseed picked up.
Date Received	<input type="text" value="10/2/2007"/>		
Date Response	<input type="text" value="10/3/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Brummett"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Buena Vista"/>		
Location	<input type="text" value="1970 Jelinda Dr"/>		
Reported Discharge	<input type="text" value="Black sludge/ hydroseed"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Valley Club"/>	Follow-up	
Observations	No evidence of discharge in creek. Small pile of hydro seed approx. 40 feet from drainage.		10/18/2007 Site visit at Valley Club to confirm cleanup of site.

Case #	<input type="text" value="07-049"/>	Response	Dropped off Pamphlets, Doorhanger and Business card. Will Follow-up.
Date Received	<input type="text" value="10/16/2007"/>		
Date Response	<input type="text" value="10/16/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text"/>		
Location	<input type="text" value="4280 Calle Real Unit 45"/>		
Reported Discharge	<input type="text" value="Paint washout"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Resident"/>	Follow-up	
Observations	Paint stains outside house in street		10/17/2007 Spoke with homeowner who denied washing paint out. Explained it was illegal to wash paint into the stormdrain and to make sure they properly dispose of paint in the sanitary sewer.

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-050"/>	Response	Spoke with Property Manager, and requested they find out where the drain is connected. (Clarifyer?)
Date Received	<input type="text" value="10/16/2007"/>		
Date Response	<input type="text" value="10/16/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text"/>		
Location	<input type="text" value="4280 Calle Real"/>		
Reported Discharge	<input type="text" value="Possible Washrack/SD connection"/>	Number of Follow-ups	<input type="text" value="1"/>
Responsible	<input type="text" value="Resident"/>	Follow-up	10/23/2007 Confirmed with property manager that the drain has a clarifier and it drains to the sanitary sewer.
Observations	Washrack with very dirty drain.		

Case #	<input type="text" value="07-051"/>	Response	Spoke with property owner asked them to clean up the manure, and gave him a Helpful Hints for Horse Owners pamphlet.
Date Received	<input type="text" value="10/17/2007"/>		
Date Response	<input type="text" value="10/17/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Brummett"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Las Palmas"/>		
Location	<input type="text" value="More Mesa/Hope Ranch"/>		
Reported Discharge	<input type="text" value="Manure pile"/>	Number of Follow-ups	<input type="text" value="1"/>

Complaints and Discoveries: 2007-2008

Responsible	<input type="text" value="Resident"/>	Follow-up	<input type="text" value="10/21/2007 Verified pile moved away from drainage area."/>
Observations	<input type="text" value="Pile of manure on property near drainage to the creek."/>		

Case #	<input type="text" value="07-052"/>	Response	<input type="text" value="Site visit - house vacant and for sale"/>
Date Received	<input type="text" value="10/17/2007"/>		
Date Response	<input type="text" value="10/18/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Brummett"/>		
Responder2	<input type="text" value="Carso"/>		
Watershed	<input type="text" value="Hospital Creek"/>		
Location	<input type="text" value="Los Feliz"/>		
Reported Discharge	<input type="text" value="Dog waste in creek"/>	Number of Follow-ups	<input type="text" value="1"/>

Responsible	<input type="text" value="Resident"/>	Follow-up	<input type="text" value="10/22/2007 Service Master hired to clean up."/>
Observations	<input type="text" value="Large amount of dog waste thrown over the fence into the creek."/>		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-053"/>	Response	Spoke with nursery owners, and they had already replaced pipe so it's no longer leaking.
Date Received	<input type="text" value="10/17/2007"/>		
Date Response	<input type="text" value="10/18/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Brummett"/>		
Watershed	<input type="text" value="Arroyo Paredon"/>		
Location	<input type="text" value="@ Via Real"/>		
Reported Discharge	<input type="text" value="Ag process water"/>	Number of Follow-ups	<input type="text" value="0"/>
Responsible	<input type="text" value="Nursery"/>	Follow-up	None required
Observations	No discharge observed		

Case #	<input type="text" value="07-054"/>	Response	Went out and cleaned it up.
Date Received	<input type="text" value="10/22/2007"/>		
Date Response	<input type="text" value="10/22/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Arroyo Burro"/>		
Location	<input type="text" value="Los Positas and Modoc"/>		
Reported Discharge	<input type="text" value="Bag of Gypsum dumped"/>	Number of Follow-ups	<input type="text" value="0"/>
Responsible	<input type="text" value="Unknown"/>	Follow-up	None required
Observations	Broken bag of Gypsum spilled in the street.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-055"/>	Response	Caller left incorrect phone number.
Date Received	<input type="text" value="10/29/2007"/>		
Date Response	<input type="text" value="10/29/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Las Palmas"/>		
Location	<input type="text" value="1000 Via Tranquila"/>		
Reported Discharge	<input type="text" value="Debris in Creek"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Property Owner"/>	Follow-up	
Observations	No debris found.		

Case #	<input type="text" value="07-056"/>	Response	Talked to contractor Jeff Jacob & assistant Isaac; house renovation work. Concrete work reportedly finished & washout cleaned out.
Date Received	<input type="text" value="10/31/2007"/>		
Date Response	<input type="text" value="10/31/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Crease"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Buena Vista"/>		
Location	<input type="text" value="151 Loureyo"/>		
Reported Discharge	<input type="text" value="Dumping concrete, yard waste"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Homeowner Pat Tsutsumida"/>	Follow-up	
Observations	Did not see evidence of concrete in creek or on bank.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-057"/>	Response	Consult with Flood Control District biologist likely an airborne bacteria. Called RP back, inquiries in with Env Health lab, UCSB and SBCC faculty say purple sulfur bacteria. Called RP with info.
Date Received	<input type="text" value="11/7/2007"/>		
Date Response	<input type="text" value="11/7/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Crease"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Arroyo Burro"/>		
Location	<input type="text" value="3523 Modoc"/>		
Reported Discharge	<input type="text" value="Fuchia colored water in creek"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Property Owner"/>	Follow-up	
Observations	Site visit. Pink material concentrated along edges of stagnant pool at base of pipes under Modoc & driveway. Partially suspended in water column, did not attach when mechanically agitated, partially coating substrate.		

Case #	<input type="text" value="07-0571"/>	Response	Spoke with manager and gave Stormwater pamphlet. They got a plumber to come and fix the issue.. Broken switch on sump pump. Confirmed the manager understood they were not to be dumping or discharging anything into the drain.
Date Received	<input type="text" value="11/14/2007"/>		
Date Response	<input type="text" value="11/14/2007"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Lloyd Simms EHS"/>		
Watershed	<input type="text" value="Turnpike Bioswale"/>		
Location	<input type="text" value="163 S. Turnpike"/>		
Reported Discharge	<input type="text" value="Food waste in clogged SD"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Vons"/>	Follow-up	
Observations	Dirty stagnant water in clogged storm drain at loading dock area.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-058"/>	Response	Met with renter William Bailey and got owners & property managers contact info. Forwarded info to Willie for graywater follow up.
Date Received	<input type="text" value="11/16/2007"/>		
Date Response	<input type="text" value="11/16/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Crease"/>		
Responder2	<input type="text" value="Brummett"/>		
Watershed	<input type="text" value="Las Canoas"/>		
Location	<input type="text" value="2150 Las Canoas"/>		
Reported Discharge	<input black="" pipe"="" type="text" value="Sudsy water coming out of 6"/>	Number of Follow-ups <input type="text" value="2"/>	
Responsible	<input type="text" value="Property Owner"/>	Follow-up	
Observations	Site visit, observed pipe, no active discharge at time of visit but evidence of previous discharge. Possible hookup to washing machine in garage.		

Case #	<input type="text" value="07-059"/>	Response	None required
Date Received	<input type="text" value="11/29/2007"/>		
Date Response	<input type="text" value="11/30/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Crease"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="More Mesa"/>		
Location	<input type="text" value="More Mesa/Hope Ranch"/>		
Reported Discharge	<input type="text" value="dumping constr matl/wood chips at More Mesa stairs"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Unknown"/>	Follow-up	
Observations	Site visit, did not see evidence of construction material, wood chips or the like at or near the base of the More Mesa stairs.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="07-060"/>	Response	Took pics and forwarded to County energy division Doug Anthony, who forwarded it to California State Lands Commission contact is Paul Mount. His phone number is (562) 590-5205 and email is mountp@slc.ca.gov. A secondary contact is Steve Fields of Division of Oil, Gas, and Geoth
Date Received	<input type="text" value="12/7/2007"/>		
Date Response	<input type="text" value="12/7/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Padaro Ln. Beach"/>		
Location	<input type="text" value="Padaro Ln. Beach"/>		
Reported Discharge	<input type="text" value="Possible oil well leaking"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Unknown"/>	Follow-up	
Observations	Oil puddle on beach.		12/14/2007 Site Visit sand had buried the area no further evidence of oil.

Case #	<input type="text" value="07-061"/>	Response	Called St. George Property Management. (805) 562-8766 6563 Trigo Rd, Isla Vista, CA Assured they would get the contractor to eliminate the discharge and clean it up.
Date Received	<input type="text" value="12/12/2007"/>		
Date Response	<input type="text" value="12/12/2007"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="IV Beach"/>		
Location	<input type="text" value="6641 Del Playa"/>		
Reported Discharge	<input type="text" value="Tile cutting washout"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Property Owner"/>	Follow-up	
Observations	Tile cutting waste water discharged down the driveway and into gutter.		12/13/2007 Confirmed it was cleaned up.

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-001"/>	Response	1/2/2008 Forwarded to EHS.
Date Received	<input type="text" value="1/2/2008"/>		
Date Response	<input type="text" value="1/2/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Lloyd"/>		
Watershed	<input type="text" value="Cieneguitas Creek"/>		
Location	<input type="text" value="El Mercado Plaza"/>		
Reported Discharge	<input type="text" value="Food waste mop bucket in back"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Restaurant"/>	Follow-up	
Observations	It appears restaurant employee has been dumping wash water onto parking lot, it appears it has been a practice for a long time as evidence by food waste build up and erosion of the asphalt.		1/4/2008 Lloyd Simms of Coutny Environmental Health Services spoke with restaurant owner/manager and issued an NOV.

Case #	<input type="text" value="08-002"/>	Response	Forwarded to Hazardous Materials.
Date Received	<input type="text" value="1/2/2008"/>		
Date Response	<input type="text" value="1/2/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Eric Carso"/>		
Responder2	<input type="text" value="Jim Morris"/>		
Watershed	<input type="text" value="Cieneguitas Creek"/>		
Location	<input type="text" value="4299 State St."/>		
Reported Discharge	<input type="text" value="Spilled oil and oil build-up"/>	Number of Follow-ups <input type="text" value="2"/>	
Responsible	<input type="text" value="Business"/>	Follow-up	
Observations	Fast Lane Oil Change had spilled oil and oil build up all over their drive approach.		1/4/2008 Jim Morris from County Hazardous Materials Unit went out and spoke with business owner about having better house keeping practices and the owner issued a memo to all employees about proper clean up and disposal of all oil spills. 1/11/2008 PCW Staff went by to look a facility and it didn't have any spills that hadn't been cleaned up.

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-003"/>	Response	Spoke with Coastal Tree Care owner Mike Hecker (896-0673) he confirmed they don't discharge anything into creeks.
Date Received	<input type="text" value="1/4/2008"/>		
Date Response	<input type="text" value="1/4/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Arroyo Burro"/>		
Location	<input type="text" value="3523 Modoc Rd."/>		
Reported Discharge	<input type="text" value="Wood chipping into creek"/>	Number of Follow-ups	<input type="text" value="0"/>
Responsible	<input type="text" value="Contractor"/>	Follow-up	None required
Observations	Unfounded complaint no wood chipping into creek only onto bank.		

Case #	<input type="text" value="08-004"/>	Response	Spoke with Store Manager Penny Amundsen and gave Creekside Concerns pamphlet. Asked her have the residue in the parking lot cleaned up.
Date Received	<input type="text" value="1/14/2008"/>		
Date Response	<input type="text" value="1/14/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Atascadero"/>		
Location	<input type="text" value="189 S. Turnpike Rd"/>		
Reported Discharge	<input type="text" value="Expired Gatoraid dumped"/>	Number of Follow-ups	<input type="text" value="1"/>
Responsible	<input type="text" value="CVS employee"/>	Follow-up	1/15/2008 Verified it was cleaned up.
Observations	Found dirty water in Turnpike Bioswale and searched up watershed and found that a drug store employee dumped 20 expired Gatoraid bottles into the parking lot and down the drain.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-005"/>	Response	Spoke with store Manager about the spill. He had it cleaned up. He said it was an accidental spill. Provided a creekside concerns pamphlet.
Date Received	<input type="text" value="1/16/2008"/>		
Date Response	<input type="text" value="1/16/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Turnpike Bioswale"/>		
Location	<input type="text" value="163 S. Turnpike"/>		
Reported Discharge	<input type="text" value="Milky substance"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Vons Employee"/>	Follow-up	
Observations	Found milky substance near drain at Vons.		

Case #	<input type="text" value="08-006"/>	Response	Homeowner confirmed he had a pan of transmission fluid that overflowed from the rain. Andrea Murphy and Jim Morris of County Haz Mat met me at site and issued notice to comply to resident which required the clean up and proof of proper disposal. Warning letter was written and mailed from Project Clean Water as well.
Date Received	<input type="text" value="1/29/2008"/>		
Date Response	<input type="text" value="1/29/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Jim Morris"/>		
Watershed	<input type="text" value="Cieneguitas Creek"/>		
Location	<input type="text" value="973 Rose Ln."/>		
Reported Discharge	<input type="text" value="Unkown pink liquid"/>	Number of Follow-ups <input type="text" value="2"/>	

Complaints and Discoveries: 2007-2008

Responsible	<input type="text" value="Resident"/>	Follow-up	
Observations	<p>RP Called Raul Yescas in Flood Control who forwarded it to us. We investigated and forwarded to Haz Mat Fire Dept. Apparent transmission fluid in block wall which was leaking out and contaminating the soil.</p>		<p>2/13/2008 Went to verify clean-up after receiving a copy of the disposal receipt. Was not completely cleaned up. Instructed property owner to completely clean up and dispose of properly and wrote second warning letter.</p> <p>2/18/2008 Follow-up inspection confirmed the property owner cleaned all the fluid properly.</p>

Case #	<input type="text" value="08-007"/>	Response	
Date Received	<input type="text" value="2/5/2008"/>		None required
Date Response	<input type="text" value="2/5/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Brummett"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Maria Ygnacio"/>		
Location	<input type="text" value="4672 Vertigo Place"/>		
Reported Discharge	<input type="text" value="Greywater irrigation"/>	Number of Follow-ups	<input type="text" value="0"/>

Responsible	<input type="text" value="Resident"/>	Follow-up	
Observations	<p>Responded and found source of smell to be a pile of fertilizing manure in neighbors yard and not a liquid discharge.</p>		None required

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-008"/>	Response	Property located in the City of Goleta. Referred RP to the City of Goleta. Bruce Page from City of Goleta said he would notify the property owner it was an illegal discharge and to eliminate it.
Date Received	<input type="text" value="2/6/2008"/>		
Date Response	<input type="text" value="2/6/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Brummett"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Devereux"/>		
Location	<input type="text" value="245 Daytona Drive"/>		
Reported Discharge	<input type="text" value="Erosion laden runoff"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Homeowner"/>	Follow-up	
Observations	None		

Case #	<input type="text" value="08-009"/>	Response	Rusti Troyna and Bruce Page of the City of Goleta and I met out at the site and gave the business owner firm warnings that what he appears to be doing is highly illegal and the site will be monitored on a regular basis and if he is caught will face enforcement action to the fullest extent of the law by the City of Goleta.
Date Received	<input type="text" value="2/13/2008"/>		
Date Response	<input type="text" value="2/13/2007"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="City of Goleta"/>		
Watershed	<input type="text" value="Los Carneros Creek"/>		
Location	<input type="text" value="158 Aero Camino"/>		
Reported Discharge	<input type="text" value="RV Sewage"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Unknown"/>	Follow-up	
Observations	Evidence of RV sewage in the creek. Located in the City of Goleta		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-010"/>	Response	Fire dept. used dirt to create a temporary berm around the storm drain inlet. However it did not appear to have entered the drain. Hazmat notified Bimbo, and had CHP stop the truck in Summerland. The truck also had a leak in Summerland at 2315 Lilly Ave. Bimbo send maint crew to fix the truck. Both spills were contained by the Fire Dept.(Isla Vista and Montecito) Spills were cleaned up by a contractor. (Advanced Cleanup Technologies Inc.)
Date Received	<input type="text" value="2/22/2008"/>		
Date Response	<input type="text" value="2/22/2007"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Matthew Chircop"/>		
Responder2	<input type="text" value="PCW Staff"/>		
Watershed	<input type="text" value="IV Beach"/>		
Location	<input type="text" value="928 Embarcadero Del Norte"/>		
Reported Discharge	<input type="text" value="Diesel Fuel"/>	Number of Follow-ups <input style="width: 50px;" type="text" value="0"/>	
Responsible	<input type="text" value="Bimbo Bakery Truck Driver"/>	Follow-up	
Observations	A delivery truck leaked diesel fuel into the parking lot during a delivery. SBCFD responded and blocked off the parking lot. Amount spread over a 20x40 foot area.		

Case #	<input type="text" value="08-011"/>	Response	Reported to Fire they responded and ordered them to clean it up. Tony Bohnett Build and Safety grading inspector responded and gave them notice they needed to reinstall BMPs on the site to prevent sediment runoff.
Date Received	<input type="text" value="2/28/2008"/>		
Date Response	<input type="text" value="2/28/2007"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Tony Bohnett & Fire"/>		
Watershed	<input type="text" value="San Ysidro Creek"/>		
Location	<input type="text" value="San Ysidro Ranch"/>		
Reported Discharge	<input type="text" value="Bucket of oil leaking"/>	Number of Follow-ups <input style="width: 50px;" type="text" value="2"/>	
Responsible	<input type="text" value="San Ysidro Ranch"/>	Follow-up	
Observations	Bucket of motor oil and used oil filter left in open stockpile yard. Failing BMPs leading to erosion of soil and stockpiles.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-012"/>	Response	Forwarded to the city and Tim Burgess reports finding no evidence of flow or source.
Date Received	<input type="text" value="3/6/2008"/>		
Date Response	<input type="text" value="3/6/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="City of Santa Barbara"/>		
Watershed	<input type="text"/>		
Location	<input type="text" value="1323 De la Guerra"/>		
Reported Discharge	<input type="text" value="Constant Flow of Water"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Unknown"/>	Follow-up	
Observations	In the City of Santa Barbara.		

Case #	<input type="text" value="08-013"/>	Response	Forwarded pictures and discoveries to Natsha Lohmus of CDFG. She said she would notify the owners if they didn't fix the problem within 2 weeks they would be cited.
Date Received	<input type="text" value="3/12/2008"/>		
Date Response	<input type="text" value="3/12/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="San Jose"/>		
Location	<input type="text" value="Near 2007 N. San Marcos Rd"/>		
Reported Discharge	<input type="text" value="Unstable bank from grading and gas and pump over creek"/>	Number of Follow-ups <input type="text" value="2"/>	
Responsible	<input type="text" value="homeowers"/>	Follow-up	
Observations	Ref complaint # 07-019 Did a follow up site visit to find that all bmps installed had failed and gas and pump still on bridge over the creek.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-015"/>	Response	Spoke with the owner and toured the facility to see how their process water system works. Asked them to shut off pipe that was discharging. Explained that this type of discharge was illegal.
Date Received	<input type="text" value="4/4/2008"/>		
Date Response	<input type="text" value="4/4/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Ocean"/>		
Location	<input type="text" value="3892 Via Real"/>		
Reported Discharge	<input type="text" value="Discharge of process water and sediments from nursery."/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Nursery workers"/>	Follow-up	
Observations	Colorama Nursery was discharging process water with sediment in it into the storm drain, which caused the culvert under Via Real to clog.		

Case #	<input type="text" value="08-016"/>	Response	Left doorhanger and Brochure. Tested waters ph and it was neutral.
Date Received	<input type="text" value="4/30/2008"/>		
Date Response	<input type="text" value="4/30/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Garnand"/>		
Watershed	<input type="text" value="Arroyo Burro"/>		
Location	<input type="text" value="605 Northview"/>		
Reported Discharge	<input type="text" value="Swimming pool Water"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Homeowner or pool man"/>	Follow-up	
Observations	Discharge of swimming pool backwash. Black pipe discharging through the fence. Dishcharge onto private property did not enter MS4.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-017"/>	Response	Spoke with the homeowner and directed them to clean up the silt and dispose of properly
Date Received	<input type="text" value="5/9/2008"/>		
Date Response	<input type="text" value="5/9/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Brummett"/>		
Watershed	<input type="text" value="Orcutt"/>		
Location	<input type="text" value="1514 Ivory"/>		
Reported Discharge	<input type="text" value="Cement saw cutt silt."/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Homeower/ Contractor"/>	Follow-up	
Observations	Saw cutt silt running down gutter for over 2 blocks.		5/12/2008 Verified proper clean up and diposal of cement saw cut silt.

Case #	<input type="text" value="08-018"/>	Response	Left educational materials for manager, and spoke with supervisor, to assure they try to be more diligent about cleaning up vehicle fluid spills.
Date Received	<input type="text" value="6/10/2008"/>		
Date Response	<input type="text" value="6/10/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="San Antonio (north)"/>		
Location	<input type="text" value="Hwy 135 Los Alamos"/>		
Reported Discharge	<input type="text" value="Possibly Auto Coolant"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Unknown"/>	Follow-up	
Observations	Photos received from RP showing what looks like rusty coolant draining into the creek at the Chevron station in Los Alamos. Site insp. found the stain from the rusty liquid at the back of the station near the air and water station		6/11/2008 Spoke with owner Bruce Smith (805-598-0909), requesting that he remind his employees to be more diligent about properly cleaning up vehilcle fluid spills. He assured me he would give a reminder to all his employees.

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-019"/>	Response	Spoke contractor who said they would clean it up ASAP.
Date Received	<input type="text" value="6/16/2008"/>		
Date Response	<input type="text" value="6/16/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Atascadero"/>		
Location	<input type="text" value="5116 Rhoads"/>		
Reported Discharge	<input type="text" value="Saw-cut silt"/>	Number of Follow-ups	<input type="text" value="1"/>
Responsible	<input type="text" value="County Contractor"/>	Follow-up	6/17/2008 Confirmed it was cleaned up.
Observations	Saw-cut silt, left by a contractor hired by the county to tear out and install new curb and gutter. Mendez Concrete Inc.525-8043.		

Case #	<input type="text" value="08-020"/>	Response	I spoke with Mark explaining that it was an illicit discharge and gave him a carpet cleaning pamphlet and asked him to clean it up. Pics G:\WATER_AG\Photos\Project Clean Water\Creekwalks and Complaints\Complaints and Discoveries\2008
Date Received	<input type="text" value="6/16/2008"/>		
Date Response	<input type="text" value="6/16/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="IV Beach"/>		
Location	<input type="text" value="Del Playa"/>		
Reported Discharge	<input type="text" value="Carpet Cleaning water"/>	Number of Follow-ups	<input type="text" value="1"/>
Responsible	<input type="text" value="Business"/>	Follow-up	6/16/2008 Returned later that afternoon to confirm it was cleaned up.
Observations	Discharged dirty carpet cleaning water into dirt along side of the house and it spilled onto driveway and into the gutter.		

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-021"/>	Response	Spoke with contractor told him to clean it up. Gave him a construction BMPs pamphlet.
Date Received	<input type="text" value="6/30/2008"/>		
Date Response	<input type="text" value="6/30/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="IV Beach"/>		
Location	<input type="text" value="6551 Del Playa"/>		
Reported Discharge	<input type="text" value="tile cuttings"/>	Number of Follow-ups <input type="text" value="2"/>	
Responsible	<input type="text" value="Homeowner"/>	Follow-up	
Observations	Saw tile cutting coming out of a drain pipe coming from a house down to the Embarcadero beach access. Tile saw on property next to drain leading from patio. Plus cement or stucco wash out on other side of property.		7/1/2008 Visited property, discharge not cleaned up. Got owners number from tennant. Spoke with owner and asked him to make sure it gets cleaned up because this is considered an illegal dishcharge. Assured me it would be clean up by following day. 7/2/2008 Confirmed clean up.

Case #	<input type="text" value="08-022"/>	Response	Spoke with cleaners and the homeowner to let them know it was illegal to allow dirty soapy water to flow into the storm drain by a commercial businesss. Gave carpet cleaners BMP guide to cleaners. Verified it was vaccumed up later that afternoon.
Date Received	<input type="text" value="6/30/2008"/>		
Date Response	<input type="text" value="6/30/2008"/>		
Source	<input type="text" value="Discovery"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="IV Beach"/>		
Location	<input type="text" value="1028 Camino Lindo"/>		
Reported Discharge	<input type="text" value="Dirty soapy water"/>	Number of Follow-ups <input type="text" value="0"/>	
Responsible	<input type="text" value="Cleaning service"/>	Follow-up	
Observations	Observed dirty soapy water flowing from a house with a clean service truck in the driveway. They were cleaning out trash cans with soap and water letting it flow into the gutter.		None required

Complaints and Discoveries: 2007-2008

Case #	<input type="text" value="08-024"/>	Response	Left door hanger pamphlet and business card.
Date Received	<input type="text" value="4/15/2008"/>		
Date Response	<input type="text" value="4/15/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Orcutt Creek"/>		
Location	<input type="text" value="Foxenwood Dr. Det Basin"/>		
Reported Discharge	<input type="text" value="Green waste Grass clippings"/>	Number of Follow-ups <input type="text" value="1"/>	
Responsible	<input type="text" value="Resident"/>	Follow-up	
Observations	Several piles of Grass Clipping and Branches appeared to have been dumped over the fence into the detention basin.		<p>4/16/2008 Wrote a warning letter and asked them to clean the green waste up and dispose of it properly. Also the resident called me and I explained it was illegal to dump green was and asked if he could get it cleaned up.</p> <p>4/18/2008 Flood control staff confirmed it was cleaned up.</p>

Case #	<input type="text" value="08-023"/>	Response	None rquired
Date Received	<input type="text" value="6/25/2008"/>		
Date Response	<input type="text" value="6/26/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Brummett"/>		
Responder2	<input type="text"/>		
Watershed	<input type="text" value="Sycamore"/>		
Location	<input type="text" value="Sycamore and Coyote Rds."/>		
Reported Discharge	<input type="text" value="Sewage odor"/>	Number of Follow-ups <input type="text" value="1"/>	

Complaints and Discoveries: 2007-2008

Responsible	<input type="text" value="Andree Clark Bird Refuge"/>	Follow-up	
Observations	<input type="text" value="Smell had travelled up from bird refuge into the low lying area of concern. However the source was not from storm drain or creeks. Creeks looked and smelled fine."/>		<input type="text" value="6/26/2008 Informed R/P of occasional 'rotten egg' odor emanates from the bird refuge and this was the source. It was not a leaking sewer."/>

Case #	<input type="text" value="08-014"/>	Response	
Date Received	<input type="text" value="3/21/2008"/>		<input type="text" value="The sherrif met me out there and told the Homeless person they had a week to get moved out. Deputy Dave Allcot 961-7574"/>
Date Response	<input type="text" value="3/21/2008"/>		
Source	<input type="text" value="Complaint"/>		
Responder1	<input type="text" value="Carso"/>		
Responder2	<input type="text" value="Sheriff"/>		
Watershed	<input type="text" value="Cieneguitas Creek"/>		
Location	<input type="text" value="Behind Uhaul Storage State"/>		
Reported Discharge	<input type="text" value="Homeless Encampment"/>	Number of Follow-ups	<input type="text" value="1"/>

Responsible	<input type="text" value="Homeless"/>	Follow-up	
Observations	<input type="text" value="Cieneguitas Creek Large homeless encampment."/>		<input type="text" value="3/28/2008 Verified encampment was cleaned up."/>